



ECool BPM Changes



- Tubes: tighter tolerances
- Feedthru plug
 - Added weld relief
 - Revised dimensions on plug and hole
- Guide plate: rounded edges
- Guide plate/pickups: deburring note - no scratches
- Pickups: wire cut only
- Feducial: for rotation
 - scribe line during mfg & reference to hole in flange
 - AND EE Support use locating fixture

Cooling Section BPM Changes



- Accommodations for magnetic measurement cart
 - Centering rings: larger ID
 - Extension of beamtube closer to end centering ring



BPM Count

□ Regular BPMs

- $22+6$ spares = **28 total**; have 17
- order $28-17=11$ new

□ Cooling Section BPMs


- $11+3$ spares = **14 total**; have none
- order 14 new




BPM Delivery/Assembly Schedule

- Parts delivered July 2 IF ORDERED NEXT WEEK
 - 4/9 requisition out for signatures/Purchasing contacts bidders
 - 4/23 bids in, award contract
 - 7/2 parts in (worst case, 10 week lead time)
 - 8/2 MSD assembly & EE Support tests complete
- In process
 - Tube: ordered & will be degassed week of 4/5
 - Flanges: will be ordered week of 4/5
 - Feedthroughs: waiting for quote
 - Scraper: preliminary design agreed upon, will order after prototype assembled

Guide Plate MB-340813



Guide Tube MB-340809



[illegible]